

Faculty Application

Installation of Snowguards on lower roof, east side of St Paul's Church, St Albans

Description of work

Addition of black powder coated snowguards with black powder coated brackets to edge of lower roof, above guttering, along full length of east side of church – i.e. between blue arrows in photo below.

This to reduce the risk of any tiles falling on carpark and pathway. Minor repairs to lower roof, guttering and downpipes will be carried out as part of the installation.



For further details please contact office@stpauls-stalbans.org